

Foto 001



Foto 006



Foto 009



Foto 012



Foto 014



Foto 015



Foto 018



Foto 025



Foto 029



Foto 031



Foto 033



Foto 037




Foto 039




Foto 041



Foto 042



Foto 043



Foto 044



Foto 045



Foto 046



Foto 047



Foto 050



Foto 053



Foto 055



Foto 057



Foto 058



Foto 059




Foto 061



Foto 062



Foto 065



Foto 066



Foto 067



Foto 068



Foto 069




Foto 070



Foto 071



Foto 073



Foto 076




Foto 078



Foto 079




Foto 081



Foto 082



Foto 084



Foto 087



Foto 088




Foto 091




Foto 092



Foto 093




Foto 094



Foto 095



Foto 099




Foto 100




Foto 101




Foto 102



Foto 103



Foto 104



Foto 105



Foto 106



Foto 107

Dueville, 16 ottobre 2023



Il Perito  
Dott. Ing. Massimo Selvatico